

Case Study



PROJECT NAME / LOCATION

Birchlands, Bridgnorth

NO 00 70 07

JOB SPECIFICS

Approx. Value

£16,000

Type of Works

Piling / Crack Repairs

Property Type

Domestic Detached Dormer Bungalow

Client / Customer




Bureau Veritas

Scope Of Works

Piling to support foundations

Works included:

Installation of 25 Piles to support existing foundations. Reinstatement of paved and areas of Tarmac that were disturbed during the piling works. Helibar repairs to external cracking. Internal Crack repairs and plaster reinstatement. Re-decorations following crack repairs.




Antares Construction Ltd

5 Campbell Street, Brockmoor, Brierley Hill, West Midlands DY5 3YG - Tel: 01384 263953 / Fax: 01384 573435

Registered In England No. 4693030 - Registered Address: Swinford House, Albion Street, Brierley Hill DY5 3EL

www.antares-ltd.co.uk


Piling Works




Piling Works carried out to stabilize existing foundations.

A Professional Design was drawn up to ascertain the required positions, quantities and depths of the piles to be used.

Following the Piling Works, the areas of paving slabs and tarmac were reinstated to match the undisturbed areas.



Crack Repair Works



Crack Repairs were carried out to the external brickwork using Thor Helical Helibars.